



912 West McGalliard
Muncie, IN 47303-1702

Phone: (765) 288-1124 (800) 551-5217 Fax: (765) 288-8378
E-mail: drh@hml.com Web Site: <http://www.hml.com>

INVOICE

Testing • Research • Consulting

INVOICE NUMBER: **155732**

INVOICE DATE: **05/13/05**

PAGE:

SOLD TO: **ERA Eagle Real Estate**
4020 Rosewood Drive
Muncie, IN 47304

SHIP TO: **ERA Eagle Real Estate**
4020 Rosewood Drive
Muncie, IN 47304

REMITTANCE COPY

SHIP VIA:
SHIP DATE: **05/13/05**
DUE DATE: **06/12/05**
TERMS: **Net 30**

CUST I.D. **EAGLER**
PO NUMBER:
PO DATE: **05/13/05**
OUR ORDER NO:
SALESPERSON:

ITEM I.D./DESC.	ORDERED	SHIPPED	UNIT	PRICE	NET	TX
3013 W CR 450 N						
Coliform Present/Absent		1		18.00	18.00	
Lead		1		25.00	25.00	
Nitrate		1		18.00	18.00	
Nitrite		1		19.00	19.00	
SA #131885-131886						

SUBTOTAL:	80.00
TAX:	0.00
PAYMENTS:	0.00
TOTAL:	80.00

If sent to collection, you will be responsible for any fees.



Testing • Research • Consulting

Chemical Analysis Report

Sample: 131886

May 16, 2005

ERA Eagle Real Estate
4020 N. Rosewood
Muncie, IN 47304

RE: PWS ID#: Unavailable
Stacey Nihart
Outside
3013 W. CR 450 N.
Muncie, IN 47304

Dear Sir/Madam:

The following are the result(s) of the test(s) performed on the sample(s) received at HML, Inc. on 05/12/2005:

<u>SAMPLE(S)</u>	<u>TEST - EPA METHOD(S)</u>	<u>RESULT(S)</u>	<u>MCL*</u>	<u>Date Completed</u>
Collected 05/12/2005 at 11:30 AM	Nitrogen, nitrate-SM 4500-NO3-D	1.2 mg/L	10 mg/L	05/12/2005
Collected 05/12/2005 at 11:30 AM	Nitrogen, Nitrite-SM 4500-NO2-B	0.040 mg/L	1 mg/L	05/12/2005


*Maximum Contaminant Level

This testing was completed by T.F. Please feel free to contact us if we can be of further service to you.

Sincerely,

Donald A. Hendrickson, Ph.D.
President - Microbiologist
Chemistry Lab #C-18-01

DAH/skp



Testing • Research • Consulting
Elemental Analysis Report

Sample: 131887

May 16, 2005

Mr. Ryan Orr
ERA Eagle Real Estate
4020 N. Rosewood
Muncie, IN 47304

RE: PWS ID#: Unavailable
Stacey Nihart
Outside
3013 W. CR 450 N.
Muncie, IN 47304

Dear Mr. Orr:

The following are the result(s) of the test(s) performed on the sample(s) received at HML, Inc. on 05/12/2005:

<u>SAMPLE(S)</u>	<u>TEST - EPA METHOD(S)</u>	<u>RESULT(S)</u>	<u>AL*</u>	<u>Date Completed</u>
Collected 05/12/2005 at 11:30 AM	Lead-200.9	0.010 mg/L	0.015 mg/L	05/12/2005

*Action Level

This testing was completed by K.K. Please feel free to contact us if we can be of further service to you.

Sincerely,

Donald A. Hendrickson, Ph.D.
President - Microbiologist
Chemistry Lab #C-18-01

DAH/skp



HOOSIER MICROBIOLOGICAL LABORATORY
912 W. MCGALLIARD RD.
MUNCIE, IN 47303
(765) 288-1124

Bacteriological Examination of Private Water

Certified by the Indiana State Board of Health
Certified Lab ID# M-18-03

Date/Time Received: 05/12/2005 at 12:30 PM

County: Delaware

Bottle Number: 131885

Organization: Stacey Nihart

Name: ERA Eagle Real Estate

Address: 3013 W. CR 450 N.

Address: 4020 N. Rosewood

City/St/Zip: Muncie, IN 47304

City/St/Zip: Muncie, IN 47304

Collected By: Ryan Orr

Telephone: (765) 741-9111

Place Collected: Outside

Started: 05/12/2005 @ 04:45 PM by Dustin

Date Collected: 05/12/2005

Read: 05/13/2005 @ 04:45 PM by Dustin

Time Collected: 11:30 AM

REPORT OF SAMPLE

TEST - METHOD

RESULT

Total Coliform-Colilert

Absent

Total Coliform Present

Absent

Fecal Coliform Present

Absent

SATISFACTORY. At examination time this water was bacteriologically safe based on USEPA standards.

UNSATISFACTORY. At examination time this water was bacteriologically unsafe.

PLEASE SUBMIT ANOTHER SAMPLE; TEST NOT VALID BECAUSE:

TOO LONG A TIME BETWEEN COLLECTION AND RECEIPT OF SAMPLE.

INVALID OR NO COLLECTION DATE AND/OR TIME.

SAMPLE LEAKED OR BROKEN IN SHIPMENT, INSUFFICIENT VOLUME

RESIDUAL CHLORINE PRESENT.

HIGH BACKGROUND COUNT.

INCORRECT SAMPLE CONTAINER.

NONCONFORMANCE WITH TEMPERATURE REQUIREMENTS > 4°C.

*MF - Membrane Filtration method

Signed: Donald A. Henderson